

# Tool changing principle and Macro program for tool changing details


Introduction in order to improve the efficiency of processing of metal-cutting machine tools, universally, configurate disc tool magazine in the vertical machining center. this type of tool magazine of the way of tool Selection is bi-directional tool selection, method of tool changing is random. The Process of Tool changing is very complex. Firstly, all of the tools should be installed on the standard shaft, after size adjustments outside of the machine, tools be stored according to a certain way in the magazine, when tool changing, firstly, select tools in the magazine, then tool Exchange device remove tools from spindle and the tool magazine. after that, the new tool will be on the spindle, the old one will be in the magazine. The tool magazine has a large capacity, it can be installed on the side or top of the headstock, and can also be installed as a separate part to the outside of the machine

## 1. Introduction for general tool magazine

Tool magazine is for keeping tools, it's a main part of the auto tool exchange device. tool magazine can be designed different types according to the number of keeping tools and the mode of drawing tools. the normally types of tool magazine showed as follows

### 1.1 liner tool magazine

The follow picture is the line tool magazine. tools are arranged like a line. the structure is simple, and the amount of tools is limited.




## 1.2 umbrella tool magazine

The picture shows as follow ,the amount of tools may be from 6 to 60.



## 1.3 chained magazine

the picture shows as follow



This type tool magazine can keep many tools ,normally more than 20 tools ,some even more than 120 tools .the chain move the tools to the fixed position ,then the robot arm move tools and fix it to spindle .

## 2Tool change principle

### 2.1 introduction for tool changing process and types:

generally ,The type of tool magazine in the CNC machine include tool magazine and machine tool spindle's motion to realize tool change or adopt manipulator to realize tool change. The way of tool changing and the structure of tool magazine effect to machine tool's productivity and reliability directly.

**Type 1:** the tool magazine and spindle relative motion realize tool change. In the process of tool changing must send the used tool back to tool magazine, and draw a new tool, this two motion can not be finish at the same time, so this way cost long time.


**Type2:** use manipulator to realize tool change, this is a popular way, because manipulator tool changing is more flexibility and save time, at present ,almost of the machining-center center are used memory random tool changing , in this way , CNC system can remember the tool number and Blade Guard position corresponding. Not matter which tool is set, it will keep remember their position and trace accordingly. And the tool magazine installs one position detect device,( generally installed with the motor), it can detect each position of blade guard,so that the tool can be take out and send back randomly. And there is mechanical origin at tool magazine, every time select tool, it will select the closest one, if it is a Disc tool magazine, each time selecting the tool the forward rotate or inversion will not exceed  $180^{\circ}$  .

### 2.2 change procedure

Here we take disc magazine(type 1 ) as an example to explain the process of using macro program to realise the tool changing . customs can refer it , first of all, according to the magazine's actual work, making a flowchart of tool changing, it can be used when make the program with macro .

#### 2. 2. 1 FLOWCHART

working flowchart:of the Disc tool magazine



## 2.2.2 SYSTEM RESOURCE CONFIGURATION

Output definition

series no.	main function	pin number
1	spindle stop accurately	9
2	disk cw output	10
3	disk ccw output	11
4	air cylinder push	12
5	spindle air cylinder push	13
6	吹气 blow	14

input definition

series no.	main function	pin number
1	spindle stop input	5
2	disk air cylinder back input	6
3	disk air cylinder push input	7
4	tool counting input	8
5	disk home signal input	9
6	spindle cut loosen input	10
7	spindle cut clamp input	11

+ configuration chart for tool magazine feature and parameter of macro-variable

series no.	Defination	Macro address
1	present tool no.	#4120
2	target tool no.	#200
3	max tool no.	#400
4	z offset	#4126

series no	Defination	Macro address
1	System tool amount	#400
2	X axis change tool position	#401
3	Y axis change tool position	#402
4	Z axis change tool position	#403
5	Z axis safety height	#404
6	Speed of change tools	#405
7	XY axis speed of change tools	#406
8	Blow delay	#407
9	Foreward delay	#408
10	Reversal delay	#409
11	No.1 Z axis tool setting position	#410
12	No.2 Z axis tool setting position	#411
13	No.3Z axis tool setting position	#412
14	No.4 Z axis tool setting position	#413
15	No.5 Z axis tool setting position	#414
16	No.6 Z axis tool setting position	#415
17	No.7 Z axis tool setting position	#416
18	No.8 Z axis tool setting position	#417
19	No.9 Z axis tool setting position	#418
20	1 No.10 Z axis tool setting position	#419
21	No.11 Z axis tool setting position	#420
22	No.12 Z axis tool setting position	#421
23	No.13 Z axis tool setting position	#422
24	No.14 Z axis tool setting position	#423
25	No.15 Z axis tool setting position	#424

26	No.16 Z axis tool setting position	#425
27	No.17 Z axis tool setting position	#426
28	No.18 Z axis tool setting position	#427
29	No.19 Z axis tool setting position	#428
30	No.20 Z axis tool setting position	#429
31	No.21 Z axis tool setting position	#430
32	.22 Z axis tool setting position	#431
33	No.23 Z axis tool setting position	#432
34	No.24 Z axis tool setting position	#433

### 3 introduction for Macro-program tool change

```

(1)O0123                                program No.
(2)G90 G599                             shift tool change use absolute programme, use G599
coordinate system, can't use in working file) )
(3)#201=#4120                            (read present tool number to #201
(4)IF[#200] == 0]GOTO 100                (##200is the ready change tool's number, the change
tool number is 0 and then quit changing tool
(5)IF[#200] == #201]GOTO 100            if present tool is the tool want to be changed
then quit
(6)IF[#400 > 24]                          (it will alarm if the system tool number exceed
24)
(7){
(8)#3000=1(warm :the setting tool exceed the max!) (system parameter no 3001 alarm, the
content can be revise)
(9)}
(10)IF[[[#200] > [#400]] || [[#201] > [#400]]]    if the current tool NO. Or aim tool NO. Is
bigger than system max tool NO., then show alarm )
(11){
(12)#3000=1 (alert: the setting tool number exceed maximum tool number!)( NO.3001 alarm appear,
can modify alarm contain)
(13)}
(14)IF[#201==0]                            if the current tool no. Was 0 ,then show alarm )
(15){
(16)#3000=1 ( present tool number is 0, error)
(17)}

```

This macro program corresponding to the flowchart “ tool change T code” , diagnose function that when system not sending tool change instruction, and detect tool number, “(2) G90 G599” ,when enter tool changing procedure, it will shift to G599 machine tool coordinate system and the values are absolutely in the program, each axis refer the machine coordinate system. so the match parameter of the tools are refer to machine coordinate , “(3 )#201=#4120” read present tool number to #201 variable, use for compare with“(5 )IF[#200] == #201]GOTO 100”, #200’s variable value is transmit by target tool number of code, if the target tool number as same as present tool

number, it will jump to N100 and not make tool change motion, if different, it will execute “(6)IF[#400 > 24]” to detect if the setting of max tool value by user exceed the max tool contain 24. over setting it will alarm: “(8)#3000=1” and stop changing tool, 10-17 is tool detect, if it is no problem it will execute the coming code.

### 3.1 z axis back to tool changing reference point

(18)G01 Z[#403+#404] F#405 (z axis rise to safe position)

This code is used for X and Y axis to avoid colliding when tool is at the position of tool changing “(19)M09”, close cooling liquid to prevent cool liquid splashing to tool head or blade guard in case of effecting tool changing precision.

### 3.2 Spindle stop accurately

Since tool installed on the spindle, cutting torque transmited can't only by bole-hole's friction, so there are one bolt at ahead of the spindle, when tool installed to spindle, the keyway of tool head must match with the bolt of spindle, and then can finish tool change, so spindle require stopping accurately at a fix angle, this is the purpose of spindle stop accurately.

(20)M89 P8 L1 start spindle stop accurately  
 (21)M89 P13 L1 (blow)  
 (22)G04 X#407 (blow delay)  
 (23)M89 P13 L0 (close blow)  
 (24)M88 P4 L0 (spindle stop accurately) (wait for spindle stop accurately position)

spindle blow use for blow off cooling liquid or piece produce by process

This code is corresponding to the flow chart “spindle accuracy stop” and make sure the spindle stop accurately.

### 3.3 X、Y AXIS POSITION TO TOOL CHANGING POINT

(25)G01 X[#401] Y[#402] F#406

Above program is for machine move to X and Y axis tool changing point, ready for tools back to tool magazine, this is corresponding to work flow chart “Spindle at the point of X/Y axis tool change”

(26)IF[#201]=0 (judge if present tool no. is 0 or not)  
 (27){ (if the value is not 0, then execute next codes 代码)  
 (28)G01 Z[#403] F#405 (machine move to Z axis tool changing point)  
 (29)M89 P11 L1 (air cylinder push)  
 (30)M88 P6 L0 (wait for disk air cylinder back input)  
 (31)M89 P12 L1 (spindle air cylinder push)  
 (32)G04 P300 (delay 300 millisecond)  
 (33)G01 Z[#403+2.5] F1000 (Z axis rise up 2.5+#403mm to prevent withhold tool disc when loose tool )  
 (34)M88 P9 L0 (wait for spindle cut loosen input)  
 (35)G01 Z[#403+#404] F#405 (Z axis rise up to safe position)  
 (36)}

Above program is simple and clear, for judge the return tool number is 0 or not, Z axis position to tool changing point, and then push out tool disc, next step is checking and waiting for

r disk air cylinder back input signal, when get this signal means handle on the spindle was block in tool disc already, and then output spindle air cylinder push signal to loose tool handle, G04 P300 delay is make sure that there is enough time to loose the tool, “G01 Z[#403+2.5] F1000”, this code is add base on customer’s tool magazine, not necessary for all tool magazine. After getting the spindle air cylinder push signal , Z axis back to safe height, ready for next tool changing.

### 3. 4 CHOOSE TOOL NEARBY

choose a tool nearby for disc tool magazine, for each selection ,the +or – direction rotate will not exceed 180° , short time and high efficiency.


(37)#1=0 (symbol for tool disc +or- rotate, #=1 is +, and #=0 is -) the default value is #=1

(38)IF[#201 > [#400/2]] GOTO 1

(if the present tool NO. is in lower half of tool magazine,the program will jump to N1)???

(39)IF[#201 >= #200] || [#200 > [#201+[#400/2]]] GOTO 2

(39) code is use for below type of tool magazine)



The present tool NO. is bigger than target tool number or target tool located at lower half of tool magazine, for example, the max tool number is 24, present tool NO. is 1, target tool NO.is 16, the nearest path is: No 1—>No 24 →-No 23...No 16

forward rotate choose tool

(40)M89 P9 L1

(disc CW output : P9 is disc CW output signal..nearby tool changing : if present tool NO. is 3 and target toolNO. is 4, disc CW)

(41)#1=0

(symbol is 0, tool selection of disc CW)

(42)GOTO 3

jump to N3

(43)N2

tool selection of ccw

(44)M89 P10 L1

( disc ccw output )

(45)#1=1

(symbol is 1, tool selection of disc CCW)


(46)GOTO 3

jump to N3

(47)N1

(48)IF[#201 >= #200 && #200 <= #400] && [#200 > [#201+#400/2]MOD#400]] GOTO 4

if the condition of program NO. (49) is established, then JUMP to N4, or execute the coming program tool selection of cw, diagram show as follow



(the present tool NO. is bigger or same as target tool NO., target tool NO. is smaller or same as system max tool NO. and both present tool N and target NO. both locat at lower half of tool magazine, for example: present tool NO. is 22 and target tool NO. is 12, it will be ccw)

(49)M89 P9 L1

(disc cw, P9 is the signal of the disc cw )

(50)#1=0

(symbol is 0, tool selection of cw)

(51)GOTO 3

jump to N3

(52)N4

(tool selection of CCW)

(53)M89 P10 L1

(54)#1=1

(symbol is 1, tool selection of cw)

### 3.5 tool selection counting

(55)N3

(56)#2=#201

(present tool NO.saved into temporary variable)

(57)WHILE[#2!=#200] DO1

(judge whether it is target tool or not )

(58)M88 P7 L0

(wait for tool counting input signal is low level )

(59)M88 P7 L1

(wait for tool counting input signal is high level)

(60)IF[#1==1] GOTO 7

jump to ccw counting

(61)#2 = #2+1 (cw add 1 each time)  
 (62)IF[#2>#400] #2=1 (if it is bigger than system tool NO. then it will recount from 1)  
 (63)GOTO 8  
 (64)N7  
 (65)#2 = #2-1 (ccw reduce 1 each time)  
 (66)IF[#2<=0] #2=#400 (if counting NO. is smaller than 0, then recount from max tool number)

(67)N8  
 (68)END1 (ending )

The programs From No (55) to (68) are for counting base on previous tool selection direction to select tool, principle is accumulation or decrease by present tool number , tool selection is finished when present tool NO. is same as target tool NO..

(69)IF[#1==1] GOTO 5 (JUMP to N5)  
 (70)G04 P#408 (dealy)  
 (71)M89 P9 L0 close disc cw output signal after delay )  
 (72)GOTO 6

(73)N5  
 (74)G04 P#409 (delay)  
 (75)M89 P10 L0 (close disc ccw output signa after delay )

Finish tool selction

The programs From (69) to (75) are for closing corresponding port according to previous tool selection direction.

tool installed to spindle

(76)N6  
 (77)M89 P11 L1 (output air cylinder push signal)  
 (78)M88 P6 L0 (waiting for disk air cylinder back input)  
 (79)M89 P13 L1 (output blow signa)  
 (80)G04 X#407 (dealy)  
 (81)M89 P13 L0 (close blow signal)  
 (82)M89 P12 L1 (output spindle air cylinder push)  
 (83)M88 P9 L0 (spindle cut loosen input )  
 (84)G01 Z[#403+2.5] F#405 (Z axis move to above the position of tool changing point 2.5mm )  
 (85)M89 P12 L0 (spindle grab tool)  
 (86)G01 Z#403 F6000 (z axis move to position of the tool changing point)  
 (87)M88 P10 L0 (spindle tool clamp input)  
 (88)M89 P11 L0 output air cylinder push signal  
 (89)M88 P5 L0 (disk air cylinder back input)  
 (90)M89 P8 L0 (spindle accuracy stop signal invalid)  
 (91)G01 Z[#403+#404] F#405 (Z axis rise to safe position)

install the chose tool into spindle 's taper suite, tool disc return

计算长度偏移量 count length excursion

(92)#2=#[409+#200] (obtain present tool's setting value)  
(93)#3=#[409+#201] (obtain previous tool's setting value)  
  
(94)#1=#2-#3 calculate two tools' length excursion)  
(95)#1=#4126-#1 (calculate length compensation)  
(96)#4126=#1 (setting length compensation)  
(97)N100 (program jump )  
(98)M30 (program ending)  
(99)%

calculate the  
D-value  
between target  
tool and  
present tool

## 4 Tool change macroprogram source code

(1 )00123 (program no.)  
(2 )G90 G599 (shift tool change use absolute  
programme, use G599 coordinate system, can't use in working file)  
(3 )#201=#4120 (read present tool number#201)  
(4 )IF[[#200] == 0]GOTO 100 (#200is the ready change tool's  
number, the change tool number is 0 and then quit and change the tool)  
(5 )IF[[#200] == #201]GOTO 100 (if present tool is the tool want  
to be change so quit and change)  
(6 )IF[#400 > 24] (it will alarm if the system tool  
number exceed 24)  
(7 ) {  
(8 )#3000=1(warm :the setting tool exceed the max!) (system parameter no. 3001  
alarm, the content can be revise)  
(9 ) }  
(10)IF[[[#200] > [#400]] || [[#201] > [#400]]] (the changing tool number and system  
present tool number exceed the biggest tool number it will alarm)  
(11) {  
(12)#3000=1(warm:the setting tool exceed the max ! ) (3001 alarm , the content can  
be revise))  
(13) }  
(14)IF[#201==0] (it will alarm if the system tool  
number is 0)  
(15) {  
(16)#3000=1(present tool number is 0, error!)  
(17) }  
(18)G01 Z[#403+#404] F#405 (Z axis raise up to safe position)  
(19)M09 (close cooling)  
(20)M89 P8 L1 (output spindle accurately stop signal)  
(21)M89 P13 L1 (blowing)  
(22)G04 X#407 (blowing delay)  
(23)M89 P13 L0 (close blowing)



(24)M88 P4 L0 (waiting spindle spindle stop input)  
(25)G01 X[#401] Y[#402] F#406 (the machine move to X、Y axis tool changing point)  
(26)IF[#201]!=0 (judge present tool number is 0 or not)  
(27) { (it will operate the below code if it is not 0)  
(28)G01 Z[#403] F#405 (the machine move to X、Y axis tool changing point)  
(29)M89 P11 L1 (output air cylinder push signal)  
(30)M88 P6 L0 (waiting for disk air cylinder push input signal)  
(31)M89 P12 L1 (output spindle air cylinder push signal)  
  
(32)G04 P300 (delay 0.3 second)  
(33)G01 Z[#403+2.5] F1000 (Z axis raise 2.5Mm)  
(34)M88 P9 L0 (waiting spindle tool loosen input )  
(35)G01 Z[#403+#404] F#405 (Z axis raise to safe position)  
(36)}  
(37)#1=0 (tool disk cw symbol)  
(38)IF[#201 > [#400/2]] GOTO 1  
(39)IF[#201 >= #200] || [#200 > [#201+#400/2]] GOTO 2  
(40)M89 P9 L1 (tool disk cw )  
(41)#1=0 (symbol is 0)  
(42)GOTO 3  
(43)N2  
(44)M89 P10 L1 (tool disk ccw output )  
(45)#1=1 (symbol is 1)  
(46)GOTO 3  
(47)N1  
(48)IF[#201 >= #200 && #200 <= #400] && [#200 > [#201+#400/2]MOD#400] GOTO 4  
(49)M89 P9 L1  
(50)#1=0  
(51)GOTO 3  
(52)N4  
(53)M89 P10 L1  
(54)#1=1  
(55)N3  
(56)#2=#201 (present tool number save a interim variable)  
(57)WHILE[#2!=#200] D01 (judge present tool is same as the target tool number)  
(58)M88 P7 L0 (waiting count signal turn low)  
(59)M88 P7 L1 (waiting tool count signal turn high)


(60) IF[#1==1] GOTO 7	(judge it is ccw or not )
(61)#2 = #2+1	(variable add1 each time)
(62) IF[#2>#400] #2=1	(turn back to 1 if the tool number
exceed system's tool number)	
(63)GOTO 8	
(64)N7	
(65)#2 = #2-1	( variable reduce 1 each time)
(66) IF[#2<=0] #2=#400	(count less than 0 and restart from
the biggest tool number)	
(67)N8	
(68)END1	(loop end key word)
(69) IF[#1==1] GOTO 5	
(70)G04 P#408	(delay)
(71)M89 P9 L0	(close disk cw signal)
(72)GOTO 6	
(73)N5	
(74)G04 P#409	(delay)
(75)M89 P10 L0	(close disk ccw signal)
(76)N6	
(77)M89 P11 L1	(output air cylinder push signal)
(78)M88 P6 L0	(wait disk air cylinder push input
(79)M89 P13 L1	(spindle blow open)
(80)G04 X#407	(spindle blow delay)
(81)M89 P13 L0	(close blow)
(82)M89 P12 L1	(spindle spindle air cylinder push signal )
(83)M88 P9 L0	(tool spindle tool loosen input position)
(84)G01 Z[#403+2.5] F#405	(Z axis move to tool changing point
(85)M89 P12 L0	(spindle catch the tool)
(86)G01 Z#403 F6000	(move to Z axis base point at the same time, prevent
spindle hold on to cutter when grabbing the tool)	
(87)M88 P10 L0	(spindle tool clamp input )
(88)M89 P11 L0	(disk ccw output back)
(89)M88 P5 L0	(disk air cylinder back input)
(90)M89 P8 L0	(spindle spindle stop accurately output signal invalid)
(91)G01 Z[#403+#404] F#405	(Z axis raise to safe position)
(92)#2=#[409+#200]	(get the present tool 's setting value)
(93)#3=#[409+#201]	(get the previous tool 's setting value)
(94)#1=#2-#3	(count these two tool's length excursion )
(95)#1=#4126-#1	(count length compensation
dosage)	
(96)#4126=#1	(setting length compensation
dosage)	
(97)N100	(program skip tab)
(98)M30	(program end)

(99)%


## 5 load tool changing macro program

After making macro program ,you need to change parameters then make the program active,,change the manage parameter 023,set it to be User-Def. after changing ,pls restart controller







COPY PROGRAM TO CONTROLLER  
 copy the program into Macro file



Lead in CSV system configuration table



When show this ,select parameter 013,and press EOB,then will show that



Then press EOB,the controller will restart